

# More grunt for less

At Mack, we're all about durability. We build our machines to last and believe that if you have an older truck on the road, you shouldn't be held back when it comes to repairs.

That's why we've rolled out our new Mack Vintage Parts program. We're now offering more affordable replacement parts such as turbochargers, coolant pumps and alternators to name a few, for Elite, Fleet-Liner, Trident, Value-Liner and Vision models.

This now means you can get more grunt for less, with the same quality guarantee.



# **Mack Deluxe Service Agreement**

When there's work to be done, your truck needs to be out on the road, not in the workshop. That's why the Mack Deluxe Service Agreement is planned to suit your operation. Wherever possible, we'll make sure you never have to turn down a job to keep up with your service schedule.

The Mack Deluxe Service Agreement lets you tailor the plan to best suit your personal needs. As well as changing all fluids and filters, the specially trained technicians will carry out the interior and exterior checks you need to avoid safety or reliability issues down the road. Service costs are set upfront at competitive rates.

To learn more about service agreement options for your Vintage truck, contact your local Mack dealer.

### **Elite / Fleet-Liner / Value-Liner**

**Model years 1994-1997** 

#### **Piston & Liner Kit**

Part No.	Note
215SB218E	VMAC I/II

#### **Engine Overhaul Kit\***

Part No.	Note	
215SB362	VMAC I/II	

#### **Oil Pump**

Part No.	Note
315GC459M2X	Standard Flow - Exchange
315GC466MX	High Flow - Exchange

#### Injector

Part No.	Note
736GB343P7X	VMAC I/II 375 HP VMAC II 400 HP - Exch
736GB343P2X	VMAC I 400 HP - Exchange
736GB343P12X	VMAC II 427/454 HP - Exchange

#### **Turbocharger**

Part No.	Note
631GC5140MX	VMAC I/II 350 400 HP - Exchange
631GC5140M2X	VMAC I/II 350 400 HP - Exchange
631GC5138MX	VMAC I/II 427/454 HP - No Stealth Brake - Exchange
631GC5145M4X	VMAC I/II 427/454 HP - Stealth Brake - Exchange

#### **Coolant Pump**

Part No.	Note
316GC3194	VMAC I/II - New
316GC284BX	VMAC I/II - Exchange

#### **Fan Clutch**

Part No.	Note
38MH322M2	Viscous Hub
25171842	Horton HT650

#### **Drive Belt**

Part No.	Note
88GB447P728	Fan Drive
25156232	Fan Drive

#### **Belt Tensioner**

Part No.	Note
20851217	VMAC I/II

#### **Ball Joints**

Part No.	Note
10QH248P4	LH Tie Rod - Mack 538 Axle
10QH248P3	RH Tie Rod - Mack 538 Axle

#### **King Pin Kit**

301SQ47E Mack 538 Axle	

#### **Rear Springs**

Part No.	Note
25159325	Spring 34000lb
25192189	Spring 38000lb
25192185	Spring 44000lb - 50"
25173594	Spring 44000lb - 55"

#### **Rear Spring Mounting**

-	
Part No.	Note
25191713	Saddle - U-Bolt 34000lb
25163352	Saddle - U-Bolt 38000lb / 44000lb
25163160	Spring Cap Lower 38000lb
25168110	Spring Cap Lower 44000lb
25167176	U-Bolt 34000 / 38000lb
25156975	U-Bolt 44000lb
25085684	Nut - U-Bolt

#### **Spring Insulator**

Part No.	Note
25121508	Upper 34000lb / 38000lb
25115012	Upper 44000lb
21036254	Lower

#### **Shock Absorber Rear Suspension**

Part No.	Note
5306-CC104	Shock Asborber 34000lb
5306-P387	Shock Asborber 38000 / 44000lb

#### **Trunion - Rear Suspension**

Part No.	Note
25163274	Trunion Upper 34000lb
25161338	Trunion Lower 34000lb
25130237	Trunion 38000 / 44000lb
25161976	Bush Trunion Polyurethane 34000lb
10QK39403M	Bush Trunion Polyurethane 34000lb
10QK255P2	Bush Trunion Brass 1pc 38000 / 44000lb
10QK255	Bush Trunion Brass 2pc 38000 / 44000lb
85QK251	Spindle Pedestal 38000 / 44000lb

<sup>\*</sup>Additional parts may be required.

IMPORTANT: Please always use chassis number to check and identify correct part number for a specific truck. Core charges may apply on exchange components.

# **Elite / Fleet-Liner / Trident / Value-Liner**

**Model years 1997-2002** 

#### **Piston & Liner Kit**

Part No.	Note
215SB219E	ETECH

#### **Engine Overhaul Kit\***

Part No.	Note	
215SB304A	ETECH	

#### **Muzzle Loader Kit**

Part No.	Note
215SB280KX	ETECH - Exchange

#### **Oil Pump**

Part No.	Note
315GC466MX	ETECH - Exchange

#### Injector

Part No.	Note
736GB415MX	ETECH 370 / 410 HP - Exchange
736GB415M2X	ETECH 435/470 HP - Exchange

#### **Electronic Unit Pump**

Part No.	Note
313GC5227MX	ETECH - Exchange

#### **Turbocharger**

Part No.	Note
631GC5144AMX	370 / 410 HP - Up to 11/00 - Exchange
631GC5174BMX	370 / 410 HP - From 12/00 - Exchange
631GC5173AMX	435 / 470 HP - Exchange

#### **Coolant Pump**

Part No.	Note
316GC3194	ETECH - New

#### **Viscous Fan Hub**

Part No.	Note
38MH322M2	ETECH

#### **Drive Belt**

Part No.	Note
88GB447P728	Fan Drive
25156232	Fan Drive

#### **Belt Tensioner**

Part No.	Note	
20851217	ETECH	

#### **Ball Joints**

Part No.	Note
10QH248P4	LH Tie Rod - Mack 538 Axle
10QH248P3	RH Tie Rod - Mack 538 Axle

#### **King Pin Kit**

Part No.	Note
301SQ47E	Mack 538 Axle



IMPORTANT: Please always use chassis number to check and identify correct part number for a specific truck. Core charges may apply on exchange components.

<sup>\*</sup>Additional parts may be required.

# Fleet-Liner / Trident / Value-Liner / Vision

Model years 2002-2007

#### **Piston & Liner Kit**

Part No.	Note	
57GC3127	CCRS	

#### **Engine Overhaul Kit\***

Part No.	Note	
85132403	CCRS	

#### **Muzzle Loader Kit**

Part No.	Note	
215SB281KX	CCRS - Exchange	

#### **Oil Pump**

Part No.	Note	
315GC466MX	CCRS - Exchange	

#### Injector

Part No.	Note
736GB420MX	CCRS Exchange Up to 08/04
736GB420M3X	CCRS Exchange From 08/04

#### **Electronic Unit Pump**

Part No.	Note
313GC5230MX	CCRS - Exchange

#### **Turbocharger**

Part No.	Note	
631GC5173AM4X	CCRS - Exchange 370 / 410 HP	
631GC5173AM9X	CCRS - Exchange 470 HP	

#### **Coolant Pump**

Part No.	Note
316GC3194	CCRS - New

#### **Fan Clutch**

Part No.	Note
85129485	CCRS

#### **Alternator**

Part No.	Note
85132185	175 Amp 12 Volt
2MJ29410	140 Amp 12 Volt Brushless

#### **Drive Belt**

Part No.	Note	
25156232	Fan Drive	
20870709	Fan Drive	

#### **Belt Tensioner**

Part No.	Note
20851217	CCRS

#### **Ball Joints**

Part No.	Note
10QH248P4	LH Tie Rod - Mack 538 Axle
10QH248P3	RH Tie Rod - Mack 538 Axle

#### **King Pin Kit**

Part No.	Note	
301SQ47F	Mack 538 Axle	



\*Additional parts may be required.

IMPORTANT: Please always use chassis number to check and identify correct part number for a specific truck. Core charges may apply on exchange components.



macktrucks.com.au PLEASE CALL: 1300 MYMACK (1300 696225)

#### Available from your participating authorised MACK dealer.

Specifications are subject to change without notice. Images are for illustration purposes only – actual products may differ from shown. VGA and/or its representatives reserve the right to correct printing errors. Please contact your local authorised dealership for full terms and conditions.